



<b>5C2F Pump</b>		
<b>Item</b>	<b>Part Number</b>	<b>Description</b>
1	P102-12-H	bolt (4)
1A	P102-24-H	bolt (4)
1B	P102-2-H	bolt (8)
2	5MU6	cover assembly
	5M31	idler pin only
12	P701-183-77	standard Viton O ring (2)
13	5M5-1	idler gear
	5M33	bushing only
14	5CU22-1.5	housing
15	5CF24	standard rotor
15A	5CF24-A	modification "A" rotor
16	5C2F2	bracket
	5MR71	bushing only
17	P203-4	nut (4)
18	5CF94-7	standard Viton seal
19	P701-223-77	standard Viton O ring
20	5C2F68	lip seal gland
21	P105-4	bolt (6)

<b>Relief Valve Option</b>		
<b>Item</b>	<b>Part Number</b>	<b>Description</b>
1	P102-12-H	bolt (3)
1A	P102-24-H	bolt (3)
1B	P102-2-H	bolt (3)
1C	P102-22-H	bolt (1)
1D	P102-6-H	bolt (1)
1E	P102-26-H	bolt (1)
2D	5C2V6-C	clockwise cover assy
	5C2V6-CC	counterclockwise assy
	5M31	idler pin only
3	5CV58-X775	plunger
4	3CV63-4	spring 30-225 psi (std)
	3CV63-5	spring 20-150 psi
	3CV63-6	spring 45-250 psi
5	P701-112-77	standard Viton O ring
5A	P701-154-77	standard Viton O ring
6	5CV56	plug
7	P350-5	ball
8	3CV63	pilot spring
9	P203-15	nut
10	P701-10-77	standard Viton O ring
11	3CV527	adjusting screw

<b>Ball Bearing Option</b>		
<b>Item</b>	<b>Part Number</b>	<b>Description</b>
15	5CFN24	rotor
20A	5C2FN68	bearing cap
20B	P602-19	ball bearing
21	P105-4	bolt (6)

<b>Reversing Feature Option</b>		
<b>Item</b>	<b>Part Number</b>	<b>Description</b>
2A	5RU35	cover
2B	5R80	spring
2C	P350-4	ball
2D	5R6	carrier assembly
	5M31	idler pin only

\*\* Pumps having date codes including and preceding D07 (i.e. C07, B07, etc.) have a different part number for item 12. If ordering a replacement bracket, housing, and/or O-ring please contact the factory.