



(Tri-Clamp Manifold not shown)

Yamada America, Inc.
955 East Algonquin Rd
Arlington Heights, IL 60005
Phone: 847.631.9200
Fax: 847.631.9273
www.yamadapump.com

Model: DP-10BSH-FDA
Part # 851848-FDA



Reference			
No.	Description	Q'ty	Part No.
1	Hexagon Socket Head Bolt	4	682971
2	Spring Lock Washer	20	681300
3	Plain Washer	20	631329
4	O-ring	8	643018
5	Valve Stopper 10EP	4	710637-EP
6	Ball	4	770931
7	Valve Seat 10EP	4	708913-EP
9	Center Disk	2	870122
13	Center Disk	2	709512
14	Sleeve	1	714678
15	O-ring	4	684900
16	Pump Base	2	710586
17	Cushion	4	771123
19	Manifold	2	831559-TC-EP
20	Body	1	715107-XP
21	Retaining Ring C Type	2	630611
22	Packing	2	684284
23	O-ring	2	640131
25	Center Rod Assembly	1	801785
26	Guide Bush	2	708502
27	Diaphragm	2	771372
28	Out Chamber	2	710660-EP
29	Spring Lock Washer	10	681855
30	Hexagon Socket Head Bolt	4	682943
31	Reinforcement Plate B	1	710636
32	Cap	1	771356
33	Spool Valve Case	1	710853-XP
34	Hexagon Socket Head Bolt	2	682918
36	Ball Valve	1	683055
37	Spool Valve Assembly	1	801404
38	Cap	1	771357
39	Reinforcement Plate A	1	710587
40	Reset Button	1	706798
41	Bolt	4	621102
42	Plain Washer	4	631328
43	Nut	4	628010
44	Gasket	1	771358
45	Hexagon Socket Head Bolt	12	682944
46	Silencer	1	682520
47	Hexagon Wrench	1	680544
48	Hexagon Socket Head Bolt	4	681297
49	Spacer	2	771380

Repair Kits**K10-SH-FDA Liquid Side Kit includes the following:**

4	O-ring	8	643018
6	Ball	4	770931
27	Diaphragm	2	771372

K115-AM Air Side Kit includes the following:

15	O-ring	4	684900
22	Packing	4	684284
23	O-ring	2	640131
37	Spool Valve Assembly	1	801404
44	Gasket	1	771358