



Customer Branded

Art. No. 10-13265-01
Replaced by

**F75B-9 Impeller pump
Art. No. 10-13153-01**

Service Kit No. 09-46691

Part no.	Description GB	Position	Quantity
01-13160-1	BODY F75B-9	1	1
01-35728	SHAFT F75B-9	2	1
01-46146	CAM 1/1 F75B	3	1
01-42443	WEARPLATE F7B/F70B	4	1
01-42400	PIN F35B-/F7B/F70B	5	1
01-46456	ENDCOVER F75B-9 VP	6	1
01-46286	GASKET F75B	7	1
01-46454	COLLAR	8	1
01-46455	RETAINING RING	9	1
0.2172.573	O-RING 23.4X3.53 BS1806 NBR70	10	1
01-46790-02	WASHER D8.2XD14X1 CU	11	1
0.0141.502	SCREW M5X8 DIN933SLOTTED BRASS	12	6
01-46794-12	SCREW M8X12 AL.BRONZE	13	1
0.3431.665	ANGULAR CONTACT BEARING 3205ATN9	14	1
0.2247.008	MECH.SEAL COMPL FA25.47.14	15	1
0.2233.008	OIL SEAL 25X40X7 BAUSL NBR	16	1
0.0370.525	EXT. CIRCLIP D25 DIN471 ST	17	3
0.0371.052	RETAIN. RING BORE D52 DIN472 SPRST	18	1
08-821B	IMPELLER F75B	19	1