

10-24334-01 Service kit

09-45585

Pump no.	Pump type	Cam/Kam No.	Thickn. (mm)	Screw	Mark on endcover
10-24334-01	F5B-9	01-42397	1.4	SKMx	10-24334-01
10-24334-02	F5B-902	01-45914	1.2	SKMx	10-24334-02

Part No.	Description GB	Position	Quantity
01-24115-5	BODY F5B-9	1	1
01-35808	SHAFT F5B-9	2	1
01-45024	GUIDE F5B-9	3	1
08-1097B	IMPELLER	4	1
01-42398	ENDCOVER F4/F5B-	5	1
01-42401	GASKET F5B-	6	1
01-42397	CAM 1/1 F5B-	7	1
01-42400	FIN F5B-/F7B/F70B	8	1
01-42399	WEAR PLATE F5B-	9	1
0.0141700	TAP BOLT M4X8 ISO4017 A2-70	10	6
01-46794-05	SCREW T0-32UNFX8 BRASS	11	1
0.2233001	LIP SEAL 16X28X7 DPSM	12	1
0.2173403	O-RING 12.3X2.4 SSI586 NBR70	13	1
0.3431761	BALL BEARING D 15 6202-2RS1 (ST)	14	2
01-45166	WASHER F5B-9	15	1

1231	P03	1/6	1/6	1/6	1/6
207	P02	1/6	1/6	1/6	1/6
100	1/6	1/6	1/6	1/6	1/6
100	1/6	1/6	1/6	1/6	1/6
100	1/6	1/6	1/6	1/6	1/6

10-24334-01 Service kit

09-45585

10-24334-01 Service kit

09-45585

10-24334-01 Service kit

09-45585