



2C2FA Pump		
Item	Part Number	Description
1	P100-17-H	bolt (4)
1A	P100-2-H	bolt (4)
	P802-5	lockwasher for above (8)
2	2MU6	cover assembly
	2M31	idler pin only
12	P701-93-77	standard Viton O ring (2)
13	2M32-1	idler gear
14	2RCU22-1.0	housing
15	2CF24	standard rotor
15A	2CF24-A	modification "A" rotor
16	2C2FA2	bracket
	2MR71	bushing only
17	P203-6	nut (4)

Relief Valve Option		
Item	Part Number	Description
1	P100-17-H	bolt (2)
1A	P100-2-H	bolt (2)
1B	P100-12-H	bolt (2)
1C	P100-26-H	bolt (1)
1D	P105-88	bolt (1)
2D	2C2V6-C	clockwise cover assy
	2M31	idler pin only
3	2CV58-A	plunger
4	2CV63-2	spring 10-200 psi
5	P701-129-77	standard Viton O ring
5A	P701-92-77	standard Viton O ring
6	2CV56	plug
7	P350-5	ball
8	2CV63-B	pilot spring
9	P203-15	nut
10	P701-10-77	standard Viton O ring
11	2CV527-A	adjusting screw

Ball Bearing Option		
Item	Part Number	Description
16A	2C2FAN2	bracket
17	P203-6	nut (4)
19	P701-222-77	standard Viton O ring
20	2C2FN68-7529	bearing cap
20A	P602-17	ball bearing
21	P105-115	bolt (5)
Note: 2C24 rotor is used with this option.		

Reversing Feature Option		
Item	Part Number	Description
2A	2RU35	cover
2B	2R80-A	spring
2C	2R6	carrier assembly
	2R31	idler pin only