




BALL BEARING PUMP

PARTS LIST MODEL 3290F 3/4" REPLACES MODEL 3290



Lip Seal Replacement
For Model 3290 only
SP 2700-06 Seal (Shaft)
SP 2000-21 "O" Ring

Replacement body for
Lip Seal Version no
longer available.

For Chrysler Ace, Crown and Royal Engines (Prior to 1950)

PART NUMBER	DESCRIPTION	QTY. REQ.
SP 1002-02	Screw (End Cover)	6
3295-01	End Cover	1
3298	Gasket	1
1210	Impeller Assembly	1
7884	Cam & Wearplate Assembly	1
SP 6080-08	Seal	1
SP 1003-01	Screw (Cam)	1
3294-01	Body	1

PART NUMBER	DESCRIPTION	QTY. REQ.
12019	Washer	1
SP 2700-18	Seal (Bearing)	1
SP 2600-07	Ball Bearing	1
SP 1700-248	Retaining Ring	1
3297-01	Shaft	1
3296	Gear Drive	1
SP 1700-62	Retaining Ring	1
SK 111-01	Service Kit	-

For Price Information, see F. ("Pumps & Parts Price Book")



JABSCO PUMP COMPANY
1485 Dale Way, Costa Mesa, California HOME OFFICE