



F95B-5000 Impeller pump 12V 2XA

Article No. 10-13143-01

Service Kit No. 09-46371

Position	Quantity	Part No.	Description
2	1	01-13131-1	Bearing housing F95B-
4	1	01-35700	Shaft F95B-5000
5	1	01-35284-2	Endcover F9B/F95B O-ring
6	1	05-06-503	O-ring
7	1	01-42423	Wearplate F8/F80/F9/F95B-
8	1	05-20-534	Mech. seal compl.
9	1	08-820B	Impeller F95B-9
10	1	01-46323	Washer F95B-
11	1	01-46322	Washer F95B-
12	1	01-35744	Cam 1/1 F95B-9
13	1	05-08-512	Ball bearing
14	1	05-08-502	Ball bearing
15	2	01-46319	Gasket F95B-
16	1	05-34-508	Retaining ring
17	1	05-34-129	Retaining ring
18	2	05-04-515	Screw
19	5	05-04-178	Screw
21	4	05-04-595	Screw
22	4	05-02-514	Washer
23	1	05-19-506	V-ring
24	1	01-42426	Pin
25	1	05-03-121	Key
26	1	05-32-1	El. magnetic clutch 12V A
28	3	05-04-158	Screw
29	3	05-01-115	Washer
30	1	05-04-150	Screw
31	1	05-02-101	Washer