

Jabsco Lite Flush - Replacement Belt Kit

Dear Customer,

In 2016 we upgraded the Lite Flush drive pulleys from plastic to aluminium, this change means the pulleys do not have to be replaced due to damage.

Only marine grade toilet paper and human waste should go through the toilet, other materials such as wet wipes or sanitary products can block and may damage the drive belt, this is not covered by warranty. Should this occur, you can now purchase a replacement belt service kit comprising of one belt and fitting instructions.

Part Number - 58542-1000

Jabsco Lite Flush Belt Replacement – 58500 Series

EN - Isolate the power supply to the toilet system - Close inlet and outlet seacocks before carrying out maintenance.
SE - Koppla bort strömförsörjningen till toaletten - Stäng både in- och utlopps bottenförskruvningar
ES - Aislar el retrete de la fuente de alimentación - Cerrar los grifos de fondo (entrada y salida)
DE - Trennen Sie die Stromversorgung der Toilette - Schließen Sie die Einlass- und Auslass-Seeventile
FR - Débrancher l'alimentation électrique du toilette - Fermez les vannes d'arrivée et d'évacuation
IT - Scollegare l'alimentazione elettrica della toilet - Chiudere i condotti di ingresso e uscita della presa a mare
NL - Ontkoppel de stroomtoevoer naar het toilet - Sluit inlaat- en uitlaatdoorvoerkranen



16. Reassemble toilet

EN - Test System
FR - Système de test
IT - Sistema di prova
DE - Prüfsystem
SE - Test system
ES - Sistema de prueba
NL - Test system

JABSCO
a xylem brand

43010-0643
Revision A

Kind Regards,

Matt Edmond
Product Manager